




Hampton Roads District



POTENTIAL IMPROVEMENTS THAT REQUIRE FURTHER STUDY		
ID#	Description	Location
1	Improve interchange configuration at U.S. 58 to remove weaving movements. (Further Study Underway)	Exit 11





Interchange Improvement Express Lanes Improvement Park & Ride Improvement



Legend

Data Sources: Virginia Department of Transportation 2019, Virginia Geographic Information Network 2019