


# I-95 Corridor Improvement Plan

## Potential Improvements that Require Further Study

Hampton Roads District



Legend

### POTENTIAL IMPROVEMENTS THAT REQUIRE FURTHER STUDY

ID #	Description	Location
1	Improve interchange configuration at U.S. 58 to remove weaving movements. (Further Study Underway)	EXIT 11
2	Expand parking at Stony Creek Park & Ride lot (Further Study Required)	EXIT 31



Interchange Improvement



Express Lanes Improvement



Park & Ride Improvement

