



ID #	Descr
1	Convert existing Express Lanes t (Further Study Required)
2	Improve interchange configurated to address safety and delay issues
3	Improve interchange configurat Road) by shortening the northb to improve spacing from adjace (Further Study Required)
4	New Park & Ride lot near Route
5	Extend the existing southbound include the ramps for the cars of auxiliary lane from the trucks of (Further Study Required)
6	Improve interchange configurat constructing a spur to the north Dale Boulevard (Further Study F
7	New Park & Ride lot near Prince Telegraph Road (Location Study
8	Improve interchange configurated to address safety and delay issues
9	New Park & Ride lot near Route (Location Study Required)
10	Improve interchange configurat County Parkway) by improving to southbound Route 286 (Furth
11	Improve interchange configurat (Franconia-Springfield Parkway) general purpose lanes (Further 2
12	Improve interchange configurate address safety and delay issues
13	Construct managed lanes from Wilson Bridge into Maryland (Fu







Data Sources: Virginia Department of Transportation 2019, Virginia Geographic Information Network 2019