


I-95 Corridor Improvement Plan

Potential Improvements that Require Further Study

Fredericksburg District



Legend

POTENTIAL IMPROVEMENTS THAT REQUIRE FURTHER STUDY

ID #	Description	Location
1	New Park & Ride lot on Ladysmith Road near I-95 (Location Study Required)	EXIT 110
2	Improve interchange configuration Construct NB I-95 C-D Road and new on-ramp from Route 17 (Further Study Required)	EXIT 126
3	Improve interchange configuration (Further Study Required)	EXIT 126
4	Expand Old Salem Church Road Park & Ride lot (Location Study Required)	EXIT 130
5	New VRE-structured Park & Ride lot near Frederick Street and Prince Edward Street (Location Study Required)	EXIT 130
6	New Park & Ride lot near U.S. 1 and Centreport Parkway (Location Study Required)	EXIT 136
7	Convert existing Express Lanes to bi-directional operations (Further Study Required)	EXIT 130 to EXIT 170
8	Improve interchange configuration (Further Study Required)	EXIT 143

■ Interchange Improvement
 ■ Express Lanes Improvement
 ■ Park & Ride Improvement



Data Sources: Virginia Department of Transportation 2019, Virginia Geographic Information Network 2019